

## **INSTALL INSTRUCTIONS C-VS-1100-F150-2**

# 2017-2022 Ford F-250, 350, 450 XL and XLT Pickup, F-450 and 550 Cab Chassis 2015-2020 Ford F-150 XL and XLT Pickup 2018-2021 Ford Expedition SSV

## Vehicle Specific Console with 11" inches of Equipment mounting space

For trucks with 40/20/40 split bench seats or 40/mini console/40 seats

\*\* Does not work with 4 X4 floor shifter or higher trim level trucks with full length center console \*\*

## **TOOLS REQUIRED:**

7 mm Socket or Driver Ratcheting wrench Panel removal tool

Metric/Standard Socket Set T-20 Torx Driver Bit 7/16" Wrench

### **INSTALLATION PARTS AND MOUNTING HARDWARE:**

QTY	DESCRIPTION		PART#	
1	Main console hous	sing		
2	Upper console mounting bracket		CM008699	
1	Lower console mo	unting bracket	CM008729	
4	1/4" Serrated nut		GSM30023	
4	1/4" Carriage bolt		GSM31999	
1	Console upper filler plate		CM008674	
2	#8-18 x ¼" Flat head screw		GSM33178	
1	USB extension cable		HW-EL-0044	
2	#4 lock washer		HW-LW-1501	CM008699
				Upper console
	VS-1100-F150-2			brackets.
Ass	sembly drawing			(One each side)
CM008674				
Filler plate for Model				
	XL truck without			Main console housing
CD player only				
CM008729				
Lower console \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\				
I	bracket			

### Always!

- ➤ Read all instructions before installing any Havis, Inc. products.
- Use hardware provided with install kit





Model XLT dashboard before installation. **Note:** Model XLT has optional CD player and model XL does not. CM008674 Filler plate is provided for XL application.



Flip up center seat and remove OEM cup holder.



Havis, Inc.
75 Jacksonville Road
Warminster, PA 18974
T 800-524-9900 F 215-957-0729

www.havis.com

Gently pry up speaker cover

If your vehicle does not have the
speaker simply lift the rubber mat
to expose the fasteners.



Remove two (2) 7mm head fasteners located next to the center channel speaker.



Pop up upper storage tray and unplug speaker.



Remove two (2) 7mm head fasteners from top of radio and HVAC controller



Starting at the top, gently pry along the radio and HVAC controller and remove.



Unclip the lower trim panel from the lower portion of the dash. Pull to the side.

It is not necessary to fully remove this panel.



Gently pry along the side vent panels around the previously removed trim bezels starting at the top and working your way down.



Remove (2) 7mm head fasteners at the top of the pocket and (2) 10mm head bolts at the bottom sides.



Pull OEM pocket out.

This will not be reused.

Remove the USB from the pocket
and plug in the provided USB extension



Havis, Inc.
75 Jacksonville Road
Warminster, PA 18974
T 800-524-9900 F 215-957-0729

Install lower console mounting bracket (CM008729) using previously removed 10mm head bolts.



Install upper console mounting brackets (CM008699) using previously removed 7mm head fasteners.



Re-install all removed trim panels and bezels.



Install console by flipping up the center seat and placing the console as close as possible to the dash and slipping it in front of the center under seat storage.



Install four (4) 1/4" x 1/2" carriage bolts and serrated nuts into the upper and lower support bracket.

Tighten all hardware. Mount USB extension in passenger side of console.



Install control heads and equipment.



For the non CD player models the CM008674 filler plate must be attached using #8 x ¾" Flat head screws on top of console.



# Instructions for Havis Remote USB Extension Cable

### Part # HW-EL-0044

#### Parts Included:

- USB 2.0 Panel Mount Extension Cable 12" length (1)
- Screws (2)
- Lock Washers (2)

### **BEFORE BEGINNING:**

(A) Ensure that 12.0" cable length is sufficient to span distance from desired USB Port to desired panel mount location.
(B) Ensure panel mount matches recommended geometry defined to the right.


### Installation:

- 1. Remove the Screws from USB Cable.
- 2. Align the female end of the USB Cable with mounting surface hole pattern.

  Insert Screws and Lock Washers as shown and tighten Screws. 
  CAUTION: DO NOT OVERTIGHTEN SCREWS



4. Strain Relief cable as needed.







1-800-524-9900